

**Search Notes****Application/Control No.**

10/771,083

**Examiner**

Toan M. Le

**Applicant(s)/Patent under Reexamination**

HOFMEISTER ET AL.

**Art Unit**

2863

**SEARCHED**

| Class | Subclass | Date      | Examiner |
|-------|----------|-----------|----------|
| 702   | 120      | 5/24/2005 | TL       |
| 372   | 38.1     | 5/12/2005 | TL       |
| 372   | 50       | 5/12/2005 | TL       |
| 257   | 688      | 5/20/2005 | TL       |
| 385   | 92       | 5/20/2005 | TL       |
| 385   | 93       | 5/20/2005 | TL       |
| 372   | 38.02    | 5/23/2005 | TL       |
|       |          |           |          |
|       |          |           |          |
|       |          |           |          |
|       |          |           |          |
|       |          |           |          |
|       |          |           |          |
|       |          |           |          |

**SEARCH NOTES  
(INCLUDING SEARCH STRATEGY)**

|   | DATE      | EXMR |
|---|-----------|------|
| Electrostatic Discharge Damage, Photodiode, Laser | 5/12/2005 | TL   |
| Laser Diode, Switch, Transceiver, Pins            | 5/12/2005 | TL   |
| Transceiver Module, Laser Diode                   | 5/12/2005 | TL   |
| VCSEL, Laser Drive, Laser Diode, Transceiver      | 5/23/2005 | TL   |
| East, Web, and NPL search                         |           |      |
|   |           |      |
|   |           |      |
|   |           |      |
|   |           |      |

**INTERFERENCE SEARCHED**

| Class | Subclass | Date | Examiner |
|-------|----------|------|----------|
|       |          |      |          |
|       |          |      |          |
|       |          |      |          |
|       |          |      |          |
|       |          |      |          |